


Prepared for: USEPA Region 1 5 Post Office Square, Suite 100 (OSRR07-2) Boston, MA 02109-3912

Prepared by: AECOM Rocky Hill CT 60148468 July 10, 2012

Building Materials Remedial Action Plan South Water Pump Station

Greenwich, CT



Prepared for: USEPA Region 1 5 Post Office Square, Suite 100 (OSRR07-2) Boston, MA 02109-3912 Prepared by: AECOM Rocky Hill CT 60148468 July 10, 2012

Building Materials Remedial Action Plan

South Water Pump Station Greenwich, CT

Prepared By: Mary Beth Hayes

malcolm a Buln

Reviewed By: Malcolm A. Beeler

Technical Advisory Review by: Chris Carleo

Contents

1.0	Intro	duction	1-
	1.1	Site Description	1- [.]
	1.2	Conceptual Site Model	1-2
	1.3	Investigation Program	1-2
	1.4	PCB Remedial Goals	1-3
	1.5	PCB Remediation Description	1-3
	1.6	Notification and Certification	1-3
	1.7	Recording on Land Records	1-4
	1.8	Remediation Schedule	1-4
2 0	Dlann	and Romadistion Branchuse	
2.0		ed Remediation Procedures	
	2.1	Paint Removal	
	2.2	Characterization Sampling Procedures	2-1
	2.3	PCB Remediation Waste Marking	2-2
	2.4	Maintenance and Monitoring	2-2
	2.5	Equipment Decontamination	2-2
	2.6	Waste Handling, Storage and Disposal	2-2
	2.7	Air Monitoring	2-3
3.0	Dama	diation Documents to	
3.0		diation Documentation	
	3.1	Field Notes	3-1
	3.2	Photographs	3-1
	3.3	Transport and Treatment/Disposal Certifications	3-1
	3.4	Remedial Action Report	3-2

AECOM Environment in

List of Tables

Table 1 - Paint Chip Analytical Data

List of Figures

Figure 1 - Site Location Map

Figure 2 - Site Plan with Sample Locations

List of Appendices

Appendix A Analytical Data Reports

Appendix B Written Certification Required Under §761.61(a)(3)(E)

1.0 Introduction

This Remedial Action Plan (RAP) has been developed for the remediation of polychlorinated biphenyls (PCBs) found in paint in the South Water Pump Station, located at 142 South Water Street in Greenwich, Connecticut. The pump station is also known as the Byram Sewage Pumping Station.

PCBs have been detected in paint at concentrations regulated under the applicable federal regulations in 40 CFR Part 761 and Connecticut state regulations under Section 22a-463 through 469, inclusive, of the Regulations of Connecticut State Agencies. Specifically, paint with total PCB concentrations equal to or greater than 50 milligram per kilogram (≥50 mg/kg) that are classified as PCB Bulk Product Waste have been identified. This RAP has been developed to address PCB-containing materials in accordance with the governing federal regulations under §761.62 and the governing state regulations.

Mechanical upgrades to the pump station systems are scheduled for initiation during the summer 2012. The PCB abatement proposed in this RAP will be conducted concurrently with the station upgrade. Paint will be removed until all visual remnants have been removed and the remaining concrete structure that was in contact with the paint will be tested to determine the PCB concentrations remaining. If PCBs are found in concrete at concentrations >1 mg/kg, a long-term maintenance and monitoring program will be implemented following the abatement activities.

1.1 Site Description

The South Water Pump Station is located at 142 South Water Street in Greenwich, Connecticut, which is approximately 73.34 degrees west longitude and 41.04 degrees north latitude. A Site Location Map is provided as **Figure 1** and a site plan indicating the station layout and sample locations is provided as **Figure 2**.

The pump station property is owned by the Town of Greenwich and was constructed in 1963. The pump station has one-floor above grade and a basement. The basement level is constructed of concrete and the above grade portion consists of brick exterior walls and concrete masonry unit (CMU) interior walls with a flat roof. The footprint of the building is approximately 700 square feet (sq ft), representing an area of 30 feet by 23.25 feet. The building basement is divided approximately equally into a wet well room and a pump room but only the pump room is painted and the wet well will not be discussed further. The first floor contains a motor room and a former chlorinator room (from previous use as wastewater treatment facility) where control and monitoring panels are currently located. The property also houses a Town of Greenwich Department of Public Works garage facility for the Highway Division and is bounded on the west by the Byram River, commercial properties to the north and south, and residences on the east.

The pump station is a low-occupancy area as no daily or routine tasks are performed within the structure. Site workers only access the building to perform corrective measures if monitoring equipment indicates a failure of the pump system or to perform maintenance on equipment. Protective measures for workers have already been implemented including

AECOM Environment 1-2

hazard communication, hazard labeling, and the use of appropriate personal protective equipment.

1.2 Conceptual Site Model

Paints were applied historically to the interior ceiling and wall surfaces of the South Water Pump Station. Based on the time frame of the building construction, it is likely that paint was applied during the timeframe when PCBs were used in paint manufacture. There are no other known sources of PCBs at the site that could have served as a source of the PCBs identified in the paint. Based on the testing performed, the paint on the interior of the structure has been determined to be a PCB Bulk Product Waste. Under 40 CFR Part 761, the use of PCBs is only allowed in a *totally enclosed manner*, which means any manner that will ensure no exposure of human beings or the environment to any concentration of PCBs. Because continued use of an "open system" is not authorized under the federal or state regulations, removal of the PCB-containing paint is required.

It has not yet been determined if PCBs have migrated into the concrete building materials to which they have been applied. Following removal of the paint the underlying building materials will be tested to determine if they are impacted by PCBs.

1.3 Investigation Program

Prior to the planned upgrades to the pump station, a sampling program for materials such as asbestos, lead and PCB-containing paints was performed to determine the potential for regulated building materials. Sample results indicated the presence of these materials and therefore additional investigation was performed in 2012.

A yellow surface paint is currently found on all of the CMU and concrete interior walls and ceilings in this structure. The yellow surface paint is not believed to be original to construction of the facility. The yellow surface paint was removed at four locations to determine if different colored paints were found beneath this surface coat and a tan-colored paint was found beneath the yellow paint at all locations.

A total of five paint chip samples were collected from the station and analyzed using EPA Methods 3540C/8082. Three samples were collected of wall paint, one sample was collected of piping paint, and one sample was collected of ceiling paint.

An initial paint chip sample was collected from the west wall of the first floor electrical room on October 3, 2010, by Malcolm Pirnie, Inc., on October 3, 2010. The sample was analyzed by EMSL Analytical Laboratory of Westmont, New Jersey. Four paint chip samples were collected on March 29, 2012 by AECOM which were analyzed by Spectrum Analytical, Inc. of Agawam, Massachusetts. All five paint chip samples contained >50 mg/kg PCBs. The concentration of PCBs detected in these samples ranged from 267 to 20,000 mg/Kg total PCBs. Aroclor 1254 was the only Aroclor detected in four of the five samples. One sample contained Aroclor 1254 and 1260. Table 1 presents the analytical results and Figure 2 indicates the sample locations. Analytical data reports are included in Appendix A.

As mentioned above, a sample of blue paint found on piping contained >50 ppm PCBs. As part of the system upgrade, all piping is to be removed from the pump station and new replacement piping will be installed.

1-3

1.4 PCB Remedial Goals

The remedial goals for PCBs are as follows:

- · Remove all PCB Bulk Product Waste paint until no visual remnants remain; and
- Perform characterization sampling (chip sampling) to determine the in-situ PCB concentration in the remaining concrete that was in contact with the paint.

If any of the concrete is determined to be a PCB Remediation Waste (e.g., contains >1 ppm PCBs):

- The PCB Remediation Waste concrete will be repainted with two coats of contrasting color paint;
- A long-term maintenance and monitoring program will be implemented as described in Section 2.3 of this RAP;
- Concentration of PCBs in the concrete will be recorded in land records; and
- A PCB M_L mark will be placed on the entrance door to the pump station.

1.5 PCB Remediation Description

All paint that is PCB Bulk Product Waste (> 50 ppm PCBs) will be removed by either chemical or physical means. The remedial standard is to be removal until no visual remnants remain. Paint removal will be conducted in conjunction with the pump station upgrade activities. In total, PCB Bulk Product Waste paint will be removed from approximately 5,400 square feet of painted surfaces (walls and ceilings). Releases of PCBs during abatement activities will be minimized through the use of engineered controls (further described in Section 2.1).

The PCB Bulk Product Waste paint and other waste materials generated by paint removal activities will be containerized in appropriate containers that will be covered or sealed when not in use. Containers will be properly labeled to indicate that the wastes contain PCBs.

1.6 Notification and Certification

This RAP serves as the Notification for PCB Remediation Activities. After having received written approval from EPA (the Approval), the Owner will notify EPA a minimum of 24 hours in advance before performing this remediation work and it will be performed as described in this Notification. However, if conditions in the Approval are more stringent than those described within this Notification, the procedures specified in the Approval shall be followed.

Attached in **Appendix B** is written certification from the Town of Greenwich Department of Public Works, as required under §761.61(a)(3)(E). The certification confirms the storage location for all reports detailing sample collection and analysis procedures used to assess or characterize PCBs at the pump station, waste handling procedures and disposal information for materials remediated under this Notification, and that these records are available for EPA inspection.

AECOM Environment 1-4

1.7 Recording on Land Records

If PCBs are identified in the concrete and CMU structures to remain following PCB abatement, their presence will be recorded on the land records. The information will be recorded on documents commonly reviewed during property transfers.

1.8 Remediation Schedule

The pump station upgrade is planned to initiate in the summer of 2012 with a proposed construction duration of approximately one-year. The PCB abatement work will be done concurrently with the upgrade construction activities. This is necessary because some painted areas at the pump station are located behind control panels and other utility-related structures. These areas will only be accessible upon removal of these structures and prior to their replacement. It should be noted that this is active pumping station that will continue to be in use throughout the duration of the upgrade and remediation program and operations cannot be terminated at any time during the project. The schedule and implementation will be performed such that the active function of the station is maintained at all times.

AECOM Environment 2-1

2.0 Planned Remediation Procedures

Remediation is planned for PCB Bulk Product Waste identified at the pump station (PCB-containing paint on interior walls and ceiling). The following is a discussion of the remedial procedures to be employed for this material.

2.1 Paint Removal

Paint will be removed using chemical and/or physical means to achieve a visual standard (e.g., no visual remnants of paint). Paint from all interior wall and ceiling surfaces throughout the pump station will be removed. The estimated surface area is approximately 5,400 square feet.

The Town of Greenwich will hire a Contractor to perform the paint removal work. The means and methods of the paint removal are to be determined by the Contractor. The Contractor shall be responsible for submitting a Contractor's Work Plan to EPA prior to commencing PCB abatement activities. This work plan shall detail means and methods to remove paint, engineered controls to prevent releases and protect clean surfaces, and any corrective measures to be implemented in the case that engineered controls are determined to have failed. The work plan shall also describe monitoring to be performed during abatement activities.

A monitoring program to be implemented inside of the building will be designed by the Contractor to conform to Occupational Safety and Health Administration guidelines. Engineered controls will be developed by the Contractor, depending upon the removal method selected, to be protective of human health and the environment.

Air monitoring will also be performed to be protective of site workers and the surrounding community. At a minimum, critical barriers will be installed on ventilation structures such as windows and louvers to prevent releases outside the building. Within the structure, unpainted floors and equipment will be covered with polyethylene sheeting to prevent potentially PCB-impacted dust or other materials from collecting on these clean surfaces.

Dust monitoring well be performed outside the structure, at a location where dust would release from the structure in the event of a failure of a critical barrier, during any dust-generating activities associated with the paint removal.

2.2 Characterization Sampling Procedures

The concrete remaining after all paint has been removed to a visual standard will be sampled to determine the concentrations of PCBs remaining at the facility. Samples will be collected and analyzed in accordance with EPA's *Standard Operating Procedure for Sampling Porous Surfaces for Polychlorinated Biphenyls (PCB)*, dated May 23, 2011. A total of six samples, three of structural concrete in the basement and three of CMUs in the first floor, will be collected. All samples will be extracted and analyzed using EPA Methods 3540C and 8082 to determine total PCBs.

AECOM Environment 2-2

2.3 PCB Remediation Waste Marking

If any of the CMU characterization samples are found to contain >1mg/kg total PCBs, the walls and ceilings of the first floor of the pump station will be painted with two coats of contrasting-color paint in accordance with the requirements of 40 CFR 761.30(p)(1)(iii)(A)(1). The same procedures will be followed for the basement of the structure if any of the concrete characterization samples contain >1 mg/kg total PCBs.

An M_L mark will be placed on the single entrance door to the facility to alert anyone present in the pump station of the presence of PCBs. Site workers shall be notified of the presence of PCBs in the structure.

2.4 Maintenance and Monitoring

A long-term maintenance and monitoring plan (MMP) will be developed and implemented at the pump station. The MMP will include the following components:

- Conduct an annual inspection to evaluate the condition of the paint and corrective actions to be performed in the case that paint is found to be worn;
- Removal and testing of any flaking paint, corrective actions to be performed to replace flaking paint, characterization requirements for the paint flakes collected, and instructions for proper disposal of the paint flakes based upon the characterization data.
- Collection of six hexane wipe samples on an annual basis. If PCBs are detected at greater than 100 ug/100 cm², corrective measures will be employed. At a minimum these corrective measures will include repainting and retesting of surfaces.

2.5 Equipment Decontamination

Non-porous surfaces on equipment, tools, and machinery that contact PCB wastes will be decontaminated prior to leaving the site or being used in the handling of clean materials. Decontamination will be done using the procedures as defined in §761.79(c)(2). Specifically, equipment, tools and machinery that are visually clean will be swabbed with solvent solution containing d-limonene. Grimy non-porous surfaces will be decontaminated following the double wash/rinse procedures specified in §761.375.

Decontamination liquids will be drummed and tested for appropriate disposal. All aqueous liquids containing 0.5 µg/L or greater total PCBs shall be shipped for treatment to an appropriately permitted facility, either the Clean Harbors facility in Bristol, CT or the United Oil facility in Bridgeport, CT. In the event that determined PCB concentrations in the decontamination liquids exceed the permit levels for these facilities, the aqueous wastes will be shipped to an appropriate disposal facility such as the Veolia Incinerator in Port Arthur, Texas. Decontamination solids (e.g., rags, brushes) will be containerized with the PCB wastes for disposal.

2.6 Waste Handling, Storage and Disposal

The means and methods for removal have not yet been determined. If the method for removal selected by the contractor involves physical removal methods (e.g., scraping,

AECOM Environment 2-3

scarification or sandblasting) all wastes will be solids and handled as described below. If paint stripping is selected then the wastes generated during paint removal will be liquid and shall be handled and disposed as described below.

All personal protective equipment (PPE) used during remediation shall be containerized as solid PCB wastes for disposal. PPE used during decontamination of equipment, tools, and machinery, as described in Section 2.5, shall also be containerized as solid PCB wastes for disposal.

Solid wastes generated during paint removal activities shall be placed directly into a lined storage container or a DOT-rated 55-gallon drum. Liquid wastes shall also be containerized in a DOT-rated 55-gallon drum. Upon first use of a storage container, an M_L mark shall be placed on the container and the date of storage will be recorded on the container by the field inspector. All waste storage containers shall be removed from the site within 30 days of their first use.

A waste storage area shall be created for the storage of the waste containers prior to their transport offsite. The waste storage area will be surrounded by temporary fencing and the fence shall have an M_L mark indicating the presence of PCB wastes. All lined storage containers or drums not actively in use shall be staged within the waste storage area and covered with a tarp or otherwise sealed to prevent storm water from entering the container.

It is estimated that approximately four cubic yards of PCB-containing paint debris will be generated and disposed of during paint removal activities. Solid PCB wastes generated during the removal of paint from the pump station will be disposed of at a non-hazardous landfill meeting the requirements of §761.62. The Contractor shall submit the landfill to be used for disposal in the Contractor's work plan to be submitted to EPA under the conditions of the Approval. Organic liquid PCB wastes will be sent to an incinerator and aqueous liquid wastes will be sent to a decontamination facility. Appropriate waste facilities for liquids are listed in Section 2.5.

Any spills or releases of PCB-contaminated materials will be remediated by the Contractor as per the requirements of Subpart G. Notification to regulatory authorities under the requirements of Subpart G, if required, will be the responsibility of the Contractor.

2.7 Air Monitoring

Air monitoring will be performed to be protective of site workers and other site users, in accordance with the facility-specific health and safety plan. Exposure limits established by the Occupational Safety and Health Administration (OSHA) will be used to protect site workers, specifically, the Permissible Exposure Limit (PEL).

3.0 Remediation Documentation

Documentation of the field remediation activities will be performed on a daily basis by the environmental contractor and a field inspector during the performance of the remedial measures. The field inspector will be responsible for completing the documentation described below. A Remedial Action Report (RAR) will be completed after the conclusion of the paint removal and abatement program. The RAR will summarize the remedial activities.

3.1 Field Notes

The field inspector will maintain a daily log of on-site activities. That log will include, but not be limited to the following.

- Health and safety meetings
- Personnel and equipment on site
- Field procedures and observations
- Paint removal progress
- Sample locations with selection criteria, samples collected, analyses performed, sample handling
- Telephone or other instructions
- Health and Safety issues
- Health and Safety monitoring data
- Estimate of wastes generated and stored and waste handling and storage procedures
- Waste transporter information

3.2 Photographs

Daily photographs will be taken of representative activities, such as paint removal, decontamination, sampling, and waste handling and storage. Copies of selected photographs with appropriate captions will be included in the RAR.

3.3 Transport and Treatment/Disposal Certifications

Manifests and/or Bills of Lading for the transportation, treatment and disposal of waste materials and certifications of the disposal of the wastes, if necessary, will be obtained from the transporter and from the treatment/disposal facility. Copies of these forms will be included in the RAR and records will be maintained in accordance with the requirements as specified in 40 CFR 761 Subpart K (PCB Waste Disposal Records and Reports).

3.4 Remedial Action Report

The Remedial Action Report (RAR) will be prepared upon completion of all remedial activities. The RAR will include, at a minimum, the following.


- Site description
- A description of field procedures
- Verification sample locations and analytical results
- A photographic record of the field activities
- Dust monitoring data
- · Waste transport and disposal information including tonnage sent to each facility
- Copies of waste manifests, bills of lading, and certificates of disposal


Any additional information required under the EPA Approval shall also be incorporated into the RAR. The report will be submitted to the EPA within 60 days of completion of remedial activities.


AECOM Environment

Table

	Town of Gree	Table 1 Paint Sample PCB Analytical Results f Greenwich South Water Pump Station, Greenwich, Connecticut	ticut
Sample Date	Material Description	Sample Location T	Total PCBs (mg/kg)
10-3-2010	Yellow paint, block wall	1st Floor electrical room – west wall south of window	20,000
3-29-2012	Yellow paint, new wall	1st Floor electrical room – north wall	382
3-29-2012	Yellow paint, Basement wall	Basement under stairwell, south wall	14,910
3-29-2012	Blue paint, piping	Basement level piping	267
3-29-2012	Yellow paint, basement ceiling	Basement ceiling, east side	8,440
	Note: Samples in bold are 469, inclusive). Samples t	Note: Samples in bold are likely to be regulated under state regulations (RCSA 22a-463 through - 469, inclusive). Samples that are shaded are regulated under federal regulations (40 CFR Part 761).	463 through - CFR Part 761).







AECOM Environment

Appendix A

Analytical Data Reports

Report Date: 16-Apr-12 10:34



SPECTRUM ANALYTICAL, INC. Featuring HANIBAL TECHNOLOGY

Laboratory Report

AECOM Environment 500 Enterprise Drive, Suite 1A Rocky Hill, CT 06067 Attn: Malcolm Beeler

Project: Southwater Pump Station - Greenwich, CT

Final Report

□ Re-Issued Report□ Revised Report

Project #: 60158736

Laboratory ID	Client Sample ID	Matrix	Date Sampled	Date Received
SB46524-01	New Wall	Paint	29-Mar-12 13:30	03-Apr-12 15:30
SB46524-02	Basement Under Stairwell	Paint	29-Mar-12 13:53	03-Apr-12 15:30
SB46524-03	Piping	Paint	29-Mar-12 14:22	03-Apr-12 15:30
SB46524-04	Basement Ceiling	Paint	29-Mar-12 14:51	03-Apr-12 15:30

I attest that the information contained within the report has been reviewed for accuracy and checked against the quality control requirements for each method. These results relate only to the sample(s) as received.

All applicable NELAC requirements have been met.

Massachusetts # M-MA138/MA1110 Connecticut # PH-0777 Florida # E87600/E87936 Maine # MA138 New Hampshire # 2538 New Jersey # MA011/MA012 New York # 11393/11840 Pennsylvania # 68-04426/68-02924 Rhode Island # 98 USDA # S-51435



Authorized by:

Nicole Leja Laboratory Director

Ticols Leja

Spectrum Analytical holds certification in the State of New York for the analytes as indicated with an X in the "Cert." column within this report. Please note that the State of New York does not offer certification for all analytes.

Please note that this report contains 10 pages of analytical data plus Chain of Custody document(s). When the Laboratory Report is indicated as revised, this report supersedes any previously dated reports for the laboratory ID(s) referenced above. Where this report identifies subcontracted analyses, copies of the subcontractor's test report are available upon request. This report may not be reproduced, except in full, without written approval from Spectrum Analytical, Inc.

Spectrum Analytical, Inc. is a NELAC accredited laboratory organization and meets NELAC testing standards. Use of the NELAC logo however does not insure that Spectrum is currently accredited for the specific method or analyte indicated. Please refer to our "Quality" web page at www.spectrum-analytical.com for a full listing of our current certifications and fields of accreditation. States in which Spectrum Analytical, Inc. holds NELAC certification are New York. New Hampshire, New Jersey and Florida. All analytical work for Volatile Organic and Air analysis are transferred to and conducted at our 830 Silver Street location (NY-11840, FL-E87936 and NJ-MA012).

CASE NARRATIVE:

The samples were received 4.3 degrees Celsius, please refer to the Chain of Custody for details specific to temperature upon receipt. An infrared thermometer with a tolerance of +/- 1.0 degrees Celsius was used immediately upon receipt of the samples.

If a Matrix Spike (MS), Matrix Spike Duplicate (MSD) or Duplicate (DUP) was not requested on the Chain of Custody, method criteria may have been fulfilled with a source sample not of this Sample Delivery Group.

Required site-specific Matrix Spike/Matrix Spike Duplicate (MS/MSD) must be requested by the client and sufficient sample must be submitted for the additional analyses. Samples submitted with insufficient volume/weight will not be analyzed for site specific MS/MSD, however a batch MS/MSD may be analyzed from a non-site specific sample.

CTDEP has published a list of analytical methods which provides a series of recommended protocols for the acquisition, analysis and reporting of analytical data in support of decisions being made utilizing the Reasonable Confidence Protocol (RCP). "Reasonable Confidence" can be established only for those methods published by the CTDEP in the RCP guidelines. The compounds and/or elements reported were specifically requested by the client on the Chain of Custody and in some cases may not include the full analyte list as defined in the method. Regulatory limits may not be achieved if specific method and/or technique was not requested on the Chain of Custody.

The CTDEP RCP requests that "all non-detects and all results below the reporting limit are reported as ND (Not Detected at the Specified Reporting Limit)". All non-detects and all results below the reporting limit are reported as "<" (less than) the reporting limit in this report.

If no reporting limits were specified or referenced on the chain-of-custody the laboratory's practical quantitation limits were applied.

Tetrachloro-m-xylene is recommended as a surrogate by the CTDEP RCP for the following SW846 Methods 8081, 8082 and 8151. Spectrum Analytical, Inc. uses Tetrachloro-m-xylene as the Internal Standard for these methods and Dibromooctaflourobiphenyl as the surrogate.

For this work order, the reporting limits have not been referenced or specified.

See below for any non-conformances and issues relating to quality control samples and/or sample analysis/matrix.

SW846 8082A

Samples:

SB46524-01

New Wall

The concentration indicated for this analyte is an estimated value. This value is considered an estimate (CLP E-flag).

Aroclor-1254 [2C]

SB46524-01RE1

New Wall

Sample dilution required for high concentration of target analytes to be within the instrument calibration range.

The surrogate recovery for this sample is not available due to sample dilution required from high analyte concentration and/or matrix interference's.

4.4-DB-Octafluorobiphenyl (Sr)

4,4-DB-Octafluorobiphenyl (Sr) [2C]

Decachlorobiphenyl (Sr)

Decachlorobiphenyl (Sr) [2C]

SB46524-02

Basement Under Stairwell

Sample dilution required for high concentration of target analytes to be within the instrument calibration range.

Sample Identification	Client Period #	Matelia	Callestian Date/Time
New Wall	Client Project #	<u>Matrix</u>	Collection Date/Time
icw wan	60158736	Paint	29-Mar-12 13:30
SB46524-01	00130730	1 din	25-14141-12 15.50

CAS No.	Analyte(s)	Result	Flag	Units	*RDL	MDL	Dilution	Method Ref.	Prepared	Analyzed	Analyst	Batch	Cer
Semivolat	ile Organic Compounds by C	GC .											
Polychlorina	ited Biphenyls												
Prepared	by method SW846 3540C												
12674-11-2	Aroclor-1016	< 209		μg/kg dry	209	105	1	SW846 8082A	06-Apr-12	10-Apr-12	IMR	1207878	X
11104-28-2	Aroclor-1221	< 209		μg/kg dry	209	189	1			(8)			Х
11141-16-5	Aroclor-1232	< 209		μg/kg dry	209	134	1		*		н	10	Х
53469-21-9	Aroclor-1242	< 209		μg/kg dry	209	123	1	•			н		X
12672-29-6	Aroclor-1248	< 209		μg/kg dry	209	103	1	*					Х
11097-69-1	Aroclor-1254	362,000	E	μg/kg dry	209	88.8	1	•			11		X
11096-82-5	Aroclor-1260	< 209		μg/kg dry	209	80.2	1	•			19	•	Х
37324-23-5	Aroclor-1262	< 209		μg/kg dry	209	195	1		*		в	10	Х
11100-14-4	Aroclor-1268	< 209		μg/kg dry	209	65.7	1	*	*	M.	11		X
Surrogate rec	overies:		×										
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr)	80			30-15	0 %				*	и		
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr) [2C]	130			30-15	0 %		•	•	и	11	•	
2051-24-3	Decachlorobiphenyl (Sr)	84			30-15	0 %		×	×				
2051-24-3	Decachlorobiphenyl (Sr) [2C]	127			30-15	0 %		*	٠				
	of Polychlorinated Biphenyls by method SW846 3540C		GS1										
12674-11-2	Aroclor-1016	< 20900		µg/kg dry	20900	10500	100	SW846 8082A	06-Apr-12	12-Apr-12	IMR	1207878	X
11104-28-2	Aroclor-1221	< 20900		μg/kg dry	20900	18900	100	и.					Х
11141-16-5	Aroclor-1232	< 20900		μg/kg dry	20900	13400	100	*					Х
53469-21-9	Aroclor-1242	< 20900		μg/kg dry	20900	12300	100	¥:			w		Х
12672-29-6	Aroclor-1248	< 20900		μg/kg dry	20900	10300	100	*			**		Х
11097-69-1	Aroclor-1254	382,000		μg/kg dry	20900	15400	100	W.	*		o.		Х
11096-82-5	Aroclor-1260	< 20900		μg/kg dry	20900	8020	100		*				Х
37324-23-5	Aroclor-1262	< 20900		μg/kg dry	20900	19500	100				"		Х
11100-14-4	Aroclor-1268	< 20900		µg/kg dry	20900	6570	100		n	•	0	н	Х
Surrogate rec	overies:												
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr)	0	S01		30-15	0 %			H				
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr) [2C]	0	S01		30-15	0 %		E	и	•			
2051-24-3	Decachlorobiphenyl (Sr)	0	S01		30-15	0 %			*		ш		
2051-24-3	Decachlorobiphenyl (Sr) [2C]	0	S01		30-15	0 %			W.				
General C	hemistry Parameters												
	MARKET OF STATE OF THE STATE OF												

Received

03-Apr-12

Piping	dentification			Client P			Matrix Paint		ection Date			ceived Apr-12	
SB46524	1-03								.v.u. 12 1 v	. 6-6-	05-1	-tpr-12	
CAS No.	Analyte(s)	Result	Flag	Units	*RDL	MDL	Dilution	Method Ref.	Prepared	Analyzed	Analyst	Batch	Cert
Semivola	tile Organic Compounds by C	GC											
Polychlorin	ated Biphenyls												
Prepared	by method SW846 3540C												
12674-11-2	Aroclor-1016	< 279		µg/kg dry	279	139	1	SW846 8082A	06-Apr-12	10-Apr-12	IMR	1207878	X
11104-28-2	Aroclor-1221	< 279		μg/kg dry	279	251	1	0.00	ж.	*	0		X
11141-16-5	Aroclor-1232	< 279		μg/kg dry	279	179	1		H	*		•	Х
53469-21-9	Aroclor-1242	< 279		µg/kg dry	279	164	1		¥				Х
12672-29-6	Aroclor-1248	< 279		μg/kg dry	279	137	1	2.4	100	*	н		Х
11097-69-1	Aroclor-1254	335,000	E	μg/kg dry	279	118	1	•			**		X
11096-82-5	Aroclor-1260	< 279		μg/kg dry	279	107	1	500	•	*			X
37324-23-5	Aroclor-1262	< 279		μg/kg dry	279	260	1						Х
11100-14-4	Aroclor-1268	< 279		μg/kg dry	279	87.6	1	w	*				х
Surrogate re	coveries:		9753100										
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr)	105			30-15	0 %		0.00		W			
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr) [2C]	95			30-15	0 %		*	*			*	
2051-24-3	Decachlorobiphenyl (Sr)	3830	S02		30-15	0 %		(m)	W.	¥			
2051-24-3	Decachlorobiphenyl (Sr) [2C]	81			30-15	0 %							
THE STATE OF THE S	of Polychlorinated Biphenyls by method SW846 3540C		GS1										
12674-11-2	Aroclor-1016	< 2790		µg/kg dry	2790	1390	10	SW846 8082A	06-Apr-12	12-Apr-12	IMR	1207878	Х
11104-28-2	Aroclor-1221	< 2790		μg/kg dry	2790	2510	10						х
11141-16-5	Aroclor-1232	< 2790		μg/kg dry	2790	1790	10			×	•	*	х
53469-21-9	Aroclor-1242	< 2790		μg/kg dry	2790	1640	10	•		н	u		х
12672-29-6	Aroclor-1248	< 2790		μg/kg dry	2790	1370	10			н	.00.0		Х
11097-69-1	Aroclor-1254	267,000		μg/kg dry	2790	2050	10			¥	10		х
11096-82-5	Aroclor-1260	< 2790		μg/kg dry	2790	1070	10						Х
37324-23-5	Aroclor-1262	< 2790		μg/kg dry	2790	2600	10			*	н	36	Х
11100-14-4	Aroclor-1268	< 2790		μg/kg dry	2790	876	10						X
Surrogate rec	coveries:	- 177			-								200
10386-84-2	4,4-DB-Octafluorobiphenyl (Sr)	105			30-150	0 %		и		×	.10		

30-150 %

30-150 %

30-150 %

SM2540 G Mod.

05-Apr-12

10386-84-2

2051-24-3

2051-24-3

4,4-DB-Octafluorobiphenyl 95

140

120

98.5

Decachlorobiphenyl (Sr)

Decachlorobiphenyl (Sr)

(Sr) [2C]

[2C]
General Chemistry Parameters
% Solids

1207710

Semivolatile Organic Compounds by GC - Quality Control

nalyte(s)	Result	Flag	Units	*RDL	Spike Level	Source Result	%REC	%REC Limits	RPD	RPI Lim
	TOME		Omis	KDL	Level	Resurt	70KEC	Limits	KFD	Lim
atch 1207878 - SW846 3540C										
Blank (1207878-BLK1)					Pre	pared: 06-Apr	12 Analyzed:	10-Apr-12		
Aroclor-1016	< 20.0		μg/kg wet	20.0						
Aroclor-1016 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1221	< 20.0		μg/kg wet	20.0						
Aroclor-1221 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1232	< 20.0		μg/kg wet	20.0						
Aroclor-1232 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1242	< 20.0		μg/kg wet	20.0						
Aroclor-1242 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1248	< 20.0		μg/kg wet	20.0						
Aroclor-1248 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1254	< 20.0		μg/kg wet	20.0						
Aroclor-1254 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1260	< 20.0		μg/kg wet	20.0						
Aroclor-1260 [2C]	< 20.0		µg/kg wet	20.0						
Aroclor-1262	< 20.0		μg/kg wet	20.0						
Aroclor-1262 [2C]	< 20.0		μg/kg wet	20.0						
Aroclor-1268 Aroclor-1268 [2C]	< 20.0 < 20.0		μg/kg wet	20.0						
1 (2)	< 20.0		μg/kg wet	20.0						
Surrogate: 4,4-DB-Octafluorobiphenyl (Sr)	14.5		μg/kg wet		20.0		72	30-150		
Surrogate: 4,4-DB-Octafluorobiphenyl (Sr) [2C]	18.1		μg/kg wet		20.0		90	30-150		
Surrogate: Decachlorobiphenyl (Sr)	15.4		μg/kg wet		20.0		77	30-150		
Surrogate: Decachlorobiphenyl (Sr) [2C]	19.4		μg/kg wet		20.0		97	30-150		
LCS (1207878-BS1)					Prep	ared: 06-Apr-	12 Analyzed:	10-Apr-12		
Aroclor-1016	203		μg/kg wet	20.0	250		81	50-140		
Aroclor-1016 [2C]	208		μg/kg wet	20.0	250		83	50-140		
Aroclor-1260	210		μg/kg wet	20.0	250		84	50-140		
Aroclor-1260 [2C]	223		μg/kg wet	20.0	250		89	50-140		
Surrogate: 4,4-DB-Octafluorobiphenyl (Sr)	15.0		μg/kg wet		20.0		75	30-150		
Surrogate: 4,4-DB-Octafluorobiphenyl (Sr) [2C]	16.9		μg/kg wet		20.0		84	30-150		
Surrogate: Decachlorobiphenyl (Sr)	17.3		μg/kg wet		20.0		86	30-150		
Surrogate: Decachlorobiphenyl (Sr) [2C]	20.8		μg/kg wet		20.0		104	30-150		
LCS Dup (1207878-BSD1)					Prep	ared: 06-Apr-	12 Analyzed:	10-Apr-12		
Aroclor-1016	218		μg/kg wet	20.0	250		87	50-140	7	30
Aroclor-1016 [2C]	219		μg/kg wet	20.0	250		87	50-140	5	30
Aroclor-1260	211		μg/kg wet	20.0	250		84	50-140	0.5	30
Aroclor-1260 [2C]	228		µg/kg wet	20.0	250		91	50-140	2	30
Surrogate: 4,4-DB-Octafluorobiphenyl (Sr)	14.8		μg/kg wet		20.0		74	30-150	lies =	
Surrogate: 4,4-DB-Octafluorobiphenyl (Sr) [2C]	16.5		μg/kg wet		20.0		82	30-150		
Surrogate: Decachlorobiphenyl (Sr)	17.7		μg/kg wet		20.0		88	30-150		
Surrogate: Decachlorobiphenyl (Sr) [2C]	21.6		μg/kg wet		20.0		108	30-150		



CHAIN OF CUSTODY RECORD

	0
1	5
	46
.Sp	5
ecial	1,1
Hame	,
Hing	P
	کے

	百	
□ Rush T/	Standard	
_	_	5
- Date	AT - 7	pecial
Needed	to 10 business day	Handling:

- All TATs subject to laboratory approval Min. 24-hour notification needed for rushes Samples disposed of after 60 days unless otherwise instructed.

	Milcolm a Ruler	Relinquished by	-	oy Basem	03 Rigino		02 Parsone	1682401 Now coll		9	XI POON Surface while X2	DW Drinking Water GW Groundwater	NallSO ₂ 9	I Na ₂ S2O ₃ 2	8	Tolephone # 860	Rocky Hill, CT OLOGF	Sco Exteport Re. Su
	wher	12/	0	Basement Coly	40	Staurucal	Parsanent under	5 =	Sample Id.	G Grab C-C			25.C	-	Drawico L	3086-472 013	c 0606	なない
	01	Re		4				3/29/12	Date	C=Composite	SO SOIL SE Studge		10-	SO, 4-HNO	C	200	+	So. 42 14
	Sander.	Received by:		14 51	1422		1353	1350	Time:		age A All	B'W Wastewater		HOEN	P.O. V			Invoice To:
		-	ber 101	6 7	0	9	5	9 7	Туре				=	6 Ascorbic Acid	P.O No. 60158736			la Same
	1/3/1	Date		11	χ,	14	×	χ,	Matrix # of V	OA Vi				ic Acad	136			ş
ALL	2 205	Tune	MAG	-	-	-	-	- *	# of Ar # of Cl # of Pl	ear Gl	ilass ass 70	Continuers:		7 CH(OH	RON			
6	43	Temp°C		+	*		7	*	3540	1008	3=		٥	List	Sam	Loc	Sile	Proj
■Ambant □ leed □ Reingensted □ Fridge temp	At-mail to wheel	EDD Formal										Analyses:	1.1.03.00	List preservative code below:	Sampler(s) MM	Location Greenwich	Sile Name: Sew throwardor	Project No.: 60158756
Offisher on the Company of the Comp	DE-mail to wheeler accom com	3						TOWN CONTROL OF THE PARTY OF TH	State specific reporting seauchirds:	Some Day Of	A Paramet T DPH RCP Report OA/OC Reporting Level	Describe MADLE VIOLE AN ROSSO	(check as apeded)	OA/OC Reporting Votes:			Her Pump Station	36

11 Aingren Drive - Agawam, MA 01001 - 413-789-9018 - FAX 413-789-4076 - www-spectrum-analytical com-



Lead & Metals Chain of Custody EMSL Order Number(Lab Use Only):

011005226

Corporate -Westmont/Cinnaminson, NJ 200 Route 130 North Cinnaminson, NJ 08077 PHONE: 1-800-220-3675 FAX: (856) 786-5974

		Name and Advanced		The state of the s	TAN. (000) 100-09	4
Company: Malcolm Pirnie, Inc.			EMSI	L-Bill to:	Same Different	
Street: 27-01 Queens Plaza North Sui	te 800	Thire	if Bill to is i d Party Billing	Dillerent note <i>requires writ</i>	instructions in Comments' ten authorization from	third party
City/State/Zip: Long Island City, NY 1	1101					ano party
Report To (Name): Toby Ledbetter		Fax:	718-446-402	0		
Telephone: 718-397-2386		-	Address: ji		oimie com	
Project Name/Number: 6869001				oasono.	2111Q.Q011	
Please Provide Results: Email Pu	rchase Order:		State S	amples Tai	ron: CT	
	naround Time (TAT)	Ontion			Nett. C1	-
3 Hour 5 Hour 24 F	lour 48 Hour	07	2 Hour	36 Hour	1 Week	2 Week
"Analysis completed Matrix	in accordance with EMSL's	Terms a			nce Gude	
The state of the s	Method		Instru	ment	Reporting Limit	Check
% by wr.	SW848-7000B/742 or AOAC 974.02		Flame Atomi	c Absorption	0.01%	X
Air	NIOSH 7082		Flame Atomi	c Absorption	4 µg/filter	
	NIOSH 7105		Graphite F	umace AA	0.03 µg/filter	
Mar.	NIOSH 7300 modific	ed	ICP-	AES	0.5 μg/filter	
Wipe* ASTM	SW846-70008/742		Flame Atomic	c Absorption	10 µg/wipe	
'If no bex is checked, non-ASTM Wipe to assumed	SW848-60108 or 0	_	ICP-/	-	0 5 µg/wipe	
TCLP	SW846-1311/7420/SM : SW846-6010B or C		Flame Atomic	m. m	0.4 mg/L (ppm)	
Soll	SW848-70008/742	-	Flame Atomic		0.1 mg/L (ppm) 40 mg/kg (ppm)	
9 3009	SW846-7421	-	Graphite Fo	The state of the s	0.3 mg/kg (ppm)	
	SW848-6010B or C		· ICP-/	NES	1 mg/kg (ppm)	
Westewater	SM3111B or SW848-70008/742	0	Flame Atomic	: Absorption	0.4 mg/L (ppm)	
	EPA 200.9		Graphite Fu		0.003 mg/L (ppm)	
Drinking Water	SW648-8010B or C	-	ICP-A		1 mg/kg (ppm)	
	EPA 200.9		Graphite Fu	1	0.003 mg/L (ppm)	
Other: PCBS	1	Prese	rvation Meth	od (Water)	- 24 4	
Name of Sampler: "On edb	ettar	Signa	ture of Samp	oter:	Lattett	
	ition	\Box	Volus	ne/Area	/ Date/Time S	empled
SW-PC-D) yellow paint.	on bock wal				10/3/10	empled
, ,		T				
		_				
		-	-			
		-				
Client Sample #'s SW-P	-,01		. To	otal # of Sa	mples:	
Relinquished (Client):	Date:	10/6/	10	Time:		
		10	/ /	Time:	11:004	
Received (Lab):	Date:					

Controlled Document - Lead & Metals CQC - LM-1.0 - 11/23/2009

Page 1 of ___ Pages



EMSL Analytical, Inc.

3 Cooper St., Westmont, NJ 08108

Phone: (856) 858-4800 Fax: (856) 858-4571 Email: jsmith@emsl.com



Attn: Toby Ledbetter Malcolm Pirnie

27-01 Queens Plaza North

Suite 800

Long Island City, NY 11101

Fax: (718) 446-4020

Phone (718) 397-2386

Project: 6869001

Customer ID:

MALC26

Customer PO: Received:

EMSL Order:

.

10/07/10 11:00 AM

011005226

Analytical Results

Client Sample Description	SW-PC-01	Collected:	10/3/	2010	Lab ID: 0001	
	Yellow paint on block wall					
Method	Parameter	Concentration	Reporting Limit	Units	Analysis Date	Analyst
3540C/8082	Araclor-1016	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1221	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1232	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1242	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Arocfor-1248	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1254	20000	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1260	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1262	ND	1300	mg/Kg	10/16/2010	eayres
3540C/8082	Aroclor-1268	ND	1300	mg/Kg	10/16/2010	eayres

Definitions:

ND - indicates that the analyte was not detected at the reporting limit

Page 2 of 2

AECOM Environment

Appendix B

Written Certification Required Under §761.61(a)(3)(E)

AMY J. SIEBERT, P.E. COMMISSIONER

DAVID P. THOMPSON, P.E. DEPUTY COMMISSIONER



Building Inspection
Building Maintenance
Engineering
Highways
Recycling
Sewers
Solid Waste Disposal
Traffic Engineering

DEPARTMENT OF PUBLIC WORKS

July 5, 2012

Kimberly N. Tisa, Region 1 PCB Coordinator United States Environmental Protection Agency 5 Post Office Square OSRR07-2 Boston, MA 02109-3912

Subject:

Written Certification as per §761.61(a)(3)(E) Building Materials Remedial Action Plan

South Water Pump Station

142 South Water Street, Greenwich, CT 06830

Dear Ms. Tisa:

I certify that all sampling plans, sample collection procedures, sample preparation procedures, extraction procedures, and instrumental/chemical analysis procedures used to assess or characterize the PCB contamination at the South Water Pump Station site, are on file at the AECOM offices located at 500 Enterprise Drive, Suite 1A, Rocky Hill, CT 06067, and are available for EPA inspection.

If you have any questions, comments, or concerns you may contact Malcolm Beeler via phone at 860-263-5806 or via email at malcolm.beeler@aecom.com.

Very Truly Yours,

Amy J. Siebert, PE Commissioner

CC:

Gary Trombly, CT DEEP

Rich Feminella, Town of Greenwich

Gary Simard, AECOM

M:\dpw\Swr\correspondence\epa\Standard Certification Letter South Water Station.docx

Town Hall, 101 Field Point Road, Greenwich, Connecticut 06836-2540

PHONE: (203) 622-7740

FAX NO. (203) 622-3716